


Vinyl Tape Mounting



1. Draw a level line and wipe mounting surface clean of dust or debris.



2. Remove tape backing.

NOTE: Be sure sign orientation is UP.



3. Align sign to level line. Apply pressure along tape line to activate pressure sensitive adhesive.

Mechanical Fastening



1. Draw a level line; align sign to this line. Transfer mounting hole pattern to wall



2. Drill and anchor at these locations.



3. Use flat head screws.

CAUTION: Do not over-tighten screws.

Insert Removal



1. Locate Suction Cup Tool (SCT) at center of Clear Lens and lift upward.



2. Pull Lens outward.



3. Remove insert. Replace insert and Clear Lens. Reverse Steps 1 & 2.